



## State Water Resources Control Board

June 19, 2018

(Via email and Certified Mail)
CERTIFIED MAIL
NO. 7017 2680 0000 6289 8893

Mr. Hugo Ceja Fleet Supervisor Merced County Fleet Services 880 Thornton Road, Building F Merced, California 95341 hceja@co.merced.ca.us

SUBJECT: NOTICE OF VIOLATION; UNDERGROUND STORAGE TANK SYSTEMS

LOCATED AT MERCED COUNTY FLEET SERVICES, 880 THORNTON ROAD.

**BUILDING F, MERCED** 

Dear Mr. Ceja:

As part of an initiative by the State Water Resources Control Board (State Water Board) to ensure compliance at government-owned and/or operated underground storage tank (UST) facilities in California, the State Water Board staff inspected the USTs at your facility on June 6, 2018, pursuant to authority under Health and Safety Code (H&SC), chapter 6.7, section 25289.

The State Water Board has identified the following violations pursuant to H&SC, chapter 6.7, and California Code of Regulations (CCR), title 23, chapter 16:

No.	Violation	Tank	Start Date	Stop Date	Regulation
1	Failure to Monitor Product Piping – The sensor in the south turbine sump was incorrectly positioned at an angle. In addition, the test boot in the south turbine sump was on and had a tube attached preventing liquid from the piping interstitial to drain into the turbine sump and be detected by the sensor. The sensor in the north turbine sump was incorrectly positioned on the wrong side of the sump and is not able to detect a leak at the earliest opportunity.	Both	June 6, 2018	Ongoing	23 CCR 2630(d)
2	Failure to Meet Under Dispenser Containment (UDC) Requirements – Both UDCs are smaller than the dispenser footprint and are not able to provide secondary containment for piping within the dispenser.	Both	June 6, 2018	Ongoing	23 CCR 2636(g)

Office of Enforcement | 801 K Street, Suite 2300 | Sacramento, CA 95814 | 916.341.5272

FELICIA MARCUS, CHAIR | EILEEN SOBECK, EXECUTIVE DIRECTOR

.

No.	Violation	Tank	Start Date	Stop Date	Regulation
3	Failure to Tag Monitoring Equipment – The automatic tank gauges did not have a current annual monitoring certification tag affixed.	Both	June 6, 2018	Ongoing	23 CCR 2638(f)
4	Failure to Maintain Site Map – The site plan in CERS does not show the location of the piping and all sensors.	Both	June 6, 2018	Ongoing	23 CCR 2711(a)(8)

You are directed to correct the ongoing violations and submit compliance documentation to the State Water Board and Merced County Environmental Health within sixty (60) days from the date of this letter. Have your Designated Operator make specific notations in the next monthly designated operator report indicating the ongoing violations have been corrected. The monthly designated operator report and any associated photos must be submitted as proof of compliance.

Please send all compliance documentation to the following:

## State Water Board

Mr. Joseph Lovesee
UST Enforcement Unit
Office of Enforcement
State Water Resources Control Board
801 K Street, Suite 2300
Sacramento, California 95814
joseph.lovesee@waterboards.ca.gov

## **Local CUPA**

Ms. Vicki Jones
Supervising Environmental Health Specialist
Merced County Environmental Health
260 E. 15<sup>th</sup> Street
Merced, California 95341
vjones@co.merced.ca.us

Pursuant to Health and Safety Code, chapter 6.7, section 25299, the owner and operator of the tank(s) are liable for a penalty of \$500 to \$5,000 per tank, per day of violation. These penalties will continue to accrue until the violations have been corrected.

If you have any questions, please contact me at (916) 341-5551, or by email at amantha.henkel@waterboards.ca.gov.

Sincerely,

Amantha Henkel

Senior Environmental Scientist

**UST Enforcement Unit** 

Office of Enforcement

cc: (v

(via email only)

Ms. Vicki Jones

Supervising Environmental Health Specialist

Merced County Environmental Health

vjones@co.merced.ca.us